AMENDMENTS TO THE SPECIFICATION:

Please replace the paragraph beginning at page 7, line 6 with the following:

Finally, Figure 4 shows a passage position through the shear with the eccentric shafts 5, 6 at their greatest separation. Here the upper hydraulic control unit 11 of the double-joint mechanism 9 is fully retracted in a position of the upper supporting lever 7 that is downwardly inclined, while the lower control unit 12 of the lower double-joint mechanism 10 is full retracted extended.

Please delete to original abstract and add the new abstract which is attached hereto on a separate sheet.